



C602 PLANNED MAINTENANCE PROGRAMS

PM PROGRAM OPTIONS

TYPE	HRS	PARTS INCLUDED	DESCRIPTION	PRICE
C602 BASIC PM PROGRAM (For units 3 years or younger)	3	<u>Kit X89311</u> <ul style="list-style-type: none">• Tune-up Kit• Scraper Blades• Syrup Pump Tube Kit	<u>INCLUDES:</u> <ul style="list-style-type: none">• Inspect operator components• Verify correct control settings• Review heat treatment performance• Calibrate syrups• Check shake dispensing mechanisms and fill sensor• Clean air filter• Check glycol fluid level• Check/adjust product to verify Gold Standard specification• Check topping heaters and water bath temperature <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• Removal of mix or syrup from machine• Labor for additional repairs (approved by store manager)• Replacing missing parts or accessories• Milkstone removal	\$545 (tax not included)



C602 PLANNED MAINTENANCE PROGRAMS

TYPE	HRS	PARTS INCLUDED	DESCRIPTION	PRICE
C602 PM PLUS PROGRAM (For units 4 years and older)	5.5	<u>Kit X89311</u> <ul style="list-style-type: none">• Tune-up Kit• Scraper Blades• Syrup Pump Tube Kit• Drive Belts• Agitator Belts• Air Filters• Brush Kits• Syrup Calibration Cup• Syrup Plug Hole Kit• Draw Valve Cap (nightcap)• Wash Bottle	<u>INCLUDES:</u> <ul style="list-style-type: none">• Interior inspection• Replace drive belts• Replace agitator belts• Inspect and clean air-cooled condensers• Replace air filters• Check air deflector and machine's air clearance• Install gauges – check/adjust refrigeration pressure settings• Inspect glycol system for leaks or filter replacement• Inspect power cord for damage and wire connections secure• Check voltage supply and secure ground connection <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• Removal of mix or syrup from machine• Removal of dried mi or syrup from inside machine• Refrigeration system repairs (refrigerant, reclaim and evacuation, supplies and tool fees, etc.)• Cleaning milkstone from hoppers, barrels or components• Worn shell bearing replacement• Torque coupling repair or replacement• Labor for additional repairs (approved by store manager)• Diagnostic time to evaluate electrical, mechanical or refrigeration system problems• Agitator cap replacement	\$945 (Tax not included)



C602 PLANNED MAINTENANCE PROGRAMS

TYPE	HRS	PARTS INCLUDED	DESCRIPTION	PRICE
8634 PM PROGRAM	6	<u>Kit X93494</u> <ul style="list-style-type: none">• Tune-Up Kit• Brush Kit• Syrup Calibration Cup• Syrup Hole Plug Kit• Draw Valve Cap (nightcap)• Wash Bottle• High Performance Taylor Lube• Syrup Valve Repair Kit• Scraper Blades• Syrup Pump Tube Kit• Drive Belts• Agitator Belts• Air Filters	<u>INCLUDES:</u> <ul style="list-style-type: none">• Interior inspection• Replace drive belts• Replace agitator belts• Inspect and clean air-cooled condensers• Replace air filters• Inspect rear shell bearing• Inspect power cord for defects• Check air deflector and machine's air clearance• Install gauges – check/adjust refrigeration pressure settings• Inspect glycol system for leaks or filter replacement• Inspect power cord for damage and wire connections secure• Check voltage supply and secure ground connection• Check agitator cap for holes or excessive wear• Inspect air compressor and dump valve for proper operation• Inspect the syrup delivery system for leaks (air and syrup), calibrate and install valve kit <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• Steam cleaning• Removal of mix or syrup from inside machine• Refrigeration system repairs (refrigerant, reclaim and evacuation, supplies and tool fees, etc.)• Cleaning milkstone from hoppers, barrels or components• Worn shell bearing replacement• Torque coupling or drive coupling repair or replacement• Labor for additional repairs (approved by store manager)• Diagnostic time to evaluate electrical, mechanical or refrigeration system problems• Agitator cap replacement	\$1,045 (tax not included)



C602 PLANNED MAINTENANCE PROGRAMS

28-DAY BRUSH BUTLER PROGRAMS – SCOPE OF WORK

Mechanical Sanitization – Brush Butler 28 Day Cleaning Cycles

<p>Product System:</p> <ul style="list-style-type: none">a. Drain product and remaining mix from the machineb. Rinse machine with cool waterc. Brush and rinse hoppers with approved cleaning/sanitation solutiond. Disassemble machine for thorough brush cleaning of the components at riske. Lubricate and reassemble machinef. Sanitize machine following assembly for operationg. Prime machine with fresh mixh. Start machine in AUTO to freeze down and check product temperature	<p>Miscellaneous Tasks Included:</p> <ul style="list-style-type: none">a. Install tune-up kit to replace wear components regularlyb. Replace scraper blades on soft serve side quarterlyc. Replace scraper blades on shake side every 6 monthsd. Replace pump tubes annually (minimum)e. Inspect/clean aluminum air filters (Model 8634)f. Inspect/clean mesh filters quarterly, replace annually (Model C602)g. Inspect drip pans for leakage/clean as neededh. Check topping bath water level/fill to marki. Record and inform manager about the amount of mix discardedj. Check/record last heat cycle datak. Check/record freezer lock occurrences since last brush cleaningl. Record freeze down time for shake and soft servem. Check product temperaturen. Check soft serve draw rate/adjust as neededo. Conduct a general inspection of the exterior of the machine
<p>Syrup System:</p> <ul style="list-style-type: none">a. Drain, rinse and sanitize the syrup linesb. Disassemble, brush clean, lubricate and sanitize syrup valvesc. Prime syrup linesd. Calibrate syrups according to the McDonald's specification	<p>Not Included:</p> <ul style="list-style-type: none">a. Equipment repairs or additional parts required during the cleaning visitb. Additional brush cleaning cycles required due to power failures, equipment malfunctions, or operational errorsc. Cleaning dried mix from exterior panels or floord. Pest infestatione. Filling cup and cone dispensers



C602 PLANNED MAINTENANCE PROGRAMS

28-DAY BRUSH BUTLER PROGRAM OPTIONS

TYPE	DESCRIPTION	ANNUAL COST
C602 KAPPUS GOLD PROGRAM Note: Serial numbers of M103 and older do not qualify for 28HT software. Ohio has now been approved for the 28HT software.	<u>INCLUDES:</u> <ul style="list-style-type: none">• 13 Brush Butler Cleanings in the year, with the software key <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• TUK or wear item parts	\$4,875
C602 KAPPUS SILVER PROGRAM Note: Serial numbers of M103 and older do not qualify for 28HT software. Ohio has now been approved for the 28HT software.	<u>INCLUDES:</u> <ul style="list-style-type: none">• 4 Brush Butler Cleanings in the year, with the software key <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• TUK or wear item parts	\$1,420
C602 KAPPUS BRONZE PROGRAM	<u>INCLUDES:</u> <ul style="list-style-type: none">• 1 Brush Butler Cleaning in the year, with the software key• MUST provide Taylor Certified Technician Badge Number to enroll in this program <u>DOES NOT INCLUDE:</u> <ul style="list-style-type: none">• TUK or wear item parts	\$355

Note: The first Brush Butler Cleaning will be completed on the same day as the PM (if PM is required).



C602 PLANNED MAINTENANCE PROGRAMS

Please provide the National Store Number, Serial Number, PM Program and Brush Butler Program requested for each applicable store and unit.

NATIONAL STORE NUMBER	UNIT SERIAL NUMBER	PM PROGRAM	BRUSH BUTLER PROGRAM

Kappus Customer Service will contact each store directly to schedule the PM (if required) and first Brush Butler Cleaning.

Authorized Signature Print Name Date

Add Alternate Contact:

Name: _____ Email: _____ Phone: _____

Please email this completed form to Kristi Bennett at McDonaldsEquip@kappuscompany.com. If you have any questions, please contact Kristi at 216-367-6640.